



155mm/39 cal 262 shots, after 30 rounds one week without oil



Condition of the barrel after 20 minutes operation with Vibrating Brush  
NOTE: Steel brush, most of carbon has left



Condition of the barrel after 20 minutes brushing, 15 minutes foam use and 10 minutes brushing, total working time 45 min

NOTE: BARREL HAS NEVER BEEN DE-COPPERED BEFORE